

Ackerman, Joyce

From:

Ackerman, Joyce

Sent:

Monday, February 12, 2018 1:35 PM

To:

Tobi L. Moore; Thomas J. Krasovec

Cc: Subject:

Neuhauser LF: Phase I metal detections

Dear Tom, Tobi, and Hunter – I talked with Curt Stovall today regarding the Phase 1 area and the overlay map which shows the surveyed excavation area and the EM-61 anomalies. Hunter asked me last week what additional area(s) needed to be excavated and/or test-pitted with regard to the anomalies in the Phase 1 area.

Hunter Butler; Stovall - CDPHE, Curtis; Sandusky, Eric

CDPHE's requirements are that all the anomalies must be investigated to determine if there are any additional buried drums. The overlay map shows anomalies outside the excavation in several locations (east, north, southwest, west, etc.). These areas need to be investigated. If the excavation area is expanded, it will need to be resurveyed and an updated overlay map created.

While this is not part of EPA's AOC, I strongly recommend that this investigation be conducted while Geosyntec and ACT/PSC are still conducting the EPA removal action.

Thank you for your assistance.

Joyce^{*}

Joyce Ackerman
On-Scene Coordinator and START P.O.
U.S. EPA Region 8
1595 Wynkoop Street
Denver, CO 80202
(303) 312-6822
Cell 303-886-1632